

1% tolerance must be used for resistors, whose tolerance is not specified



1% tolerance must be used for resistors, whose tolerance is not specified